

Dacia Logan

VIN: UU1DJF00270202476

Benzină

2022

Generat pe 2024-12-29 12:28



Odometru

✓ Arată bine



Statut legal

✓ Arată bine



Daune

⚠ Necesită atenție



+31

Surse de date

Am verificat 900+ de surse de date în 35 de țări

Furt

Vehiculul este în prezent marcat ca furat? A fost furat în trecut? A fost recuperat?



Nu s-au găsit probleme

Nu am găsit nicio înregistrare că vehiculul a fost furat.



Notă

Verificarea bazei de date a poliției privind vehiculele furate finalizată în 8 țări:  +2

Iată ce am verificat:



Căutat drept furat

✓ Nu s-a găsit nici o înregistrare



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Starea actuală necunoscută



Furat în trecut

✓ Nu s-a găsit nici o înregistrare

Vehiculul a fost recuperat

Baza de date aparținând poliției cu vehicule furate, **verificare finalizată în:**



România



Italia



Lituania




Odometru

Există semne conform cărora kilometrajul a fost dat înapoi sau discrepanțe ale kilometrajului?



Notă

Ultimul kilometraj cunoscut: 36.936 km



Disclaimer (declinarea responsabilității): acest grafic reprezintă o tendință estimată a kilometrajului. Deși se bazează pe înregistrări reale de kilometraj disponibile pentru acest vehicul, există lacune având în vedere că evoluția kilometrajului nu este înregistrată în mod constant. Pentru a lua în considerare aceste date lipsă, aplicăm un model patentat de analiză a datelor care prezice modul în care probabil s-a schimbat kilometrajul între evenimentele înregistrate. Acest lucru ajută la furnizarea unei imagini mai complete a utilizării vehiculului în timp.

Statut legal

A trecut vehiculul inspecțiile tehnice? A fost notat drept casat?



Nu s-au găsit probleme

Nu s-au găsit înregistrări despre statutul legal al acestui vehicul

Legal



Inspecție tehnică periodică (ITP)

✓ Nu s-a găsit nici o înregistrare

Nu au fost găsite înregistrări ale inspecției tehnice



Casat

✓ Nu s-a găsit nici o înregistrare

Nu există nici o înregistrare că vehiculul a fost marcat drept casat

Daune

Acest vehicul a fost avariat în trecut ? Care a fost valoarea daunelor?



Ai grijă!

Acest vehicul a fost avariat



Notă

Daunele minore nu vor afecta în mod normal siguranța vehiculului și nu vor cauza probleme structurale

Înregistrări de daune



Daune frontale:

Față / Bară de protecție

Față dreapta / Bară de protecție

Daune pe partea dreaptă:

Dreapta / Portieră față

Daune pe partea stângă:

Spate / Bară de protecție

Spate stânga / Bară de protecție

Spate dreapta / Bară de protecție

Alte daune:

Exterior / Neclasificat

Interior / Neclasificat

2023-09

România

Daune

Costul estimativ al reparațiilor

24.001 RON – 48.000 RON

Cauza posibilă a daunelor

Necunoscut

Categorii de daune

Părți exterioare ale caroseriei

Iluminat exterior

Sisteme de siguranță pasive

Elemente structurale ale caroseriei

Tapiterie

Disclaimer (declinarea responsabilității): Majoritatea înregistrărilor de daune sunt legate de accidente, dar uneori nu este acesta cazul. Unele înregistrări provin din alte surse cum ar fi serviceurile specializate pe lucrări de caroserie, cereri de daune, licitații sau inspecții ale vehiculelor. Aceste înregistrări arată că starea vehiculului a fost evaluată, chiar dacă nu a fost din cauza unui accident.

Dezastre naturale

Locația vehiculului a fost înregistrată în zona unui dezastru natural?



Nu s-au găsit probleme

Locația vehiculului nu a fost înregistrată în zona unui dezastru natural

Valoarea de piață

Cu cât s-a vândut vehiculul în trecut? Care este în medie prețul vehiculelor din acest model și an?

Notă

- Prețul mediu de pe piață pentru un astfel de vehicul: 66.267 RON
- Atenție la problemele ascunse dacă vehiculul a fost la vânzare la un preț semnificativ mai mic decât prețul actual!

Valoarea de piață azi pentru Dacia Logan 2022

Valoarea de piață este determinată prin examinarea prețului unui anumit model de mașină (fabricat în același an) în țara în care a fost generat raportul. Analizăm datele din ultimele 6 luni.

Cel mai mic preț

63.908 RON

Prețul mediu

66.267 RON

Cel mai mare preț

69.438 RON

Emisii

Câte emisii de CO₂ produc vehiculele din acest model/an?

Notă

Emisii CO₂: A (106 g/km)

Emisii CO₂

Emisiile CO₂ ale
vehiculului tău

106 g/km Clasă **A**

Până la 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 și peste

Emisii CO₂ g/km

Specificații și echipare

Ce specificații și echipamente sunt înregistrate pentru acest vehicul?

Notă

Verificați dacă specificațiile și echipamentul acestui vehicul se potrivesc cu datele furnizate de vânzător.

Identificare și specificații tehnice



Producător

Dacia



Model

Logan



Descriere

Logan-Sandero 3 / Taliant (Xjf)



Tip caroserie

Sedan



An de fabricație

2022



Capacitate cilindrică

1 l



Putere motor

74 kW (99 cp)



Tip combustibil

Benzină



Tip transmisie

Tracțiune față (FWD)



Culoare

Alb



Nr. locuri

5



Cod motor

H4D-F4



Categorie

m1



Omologare

e19*2007/46*0026*15



Masă maximă autorizată

2.705 kg

Echipare

Cum a fost primit de la producător

ACCESSORY SOCKET

WITHOUT ACCESSORY SOCKET (SSPACC)

ADDITIONAL HEADLIGHTS

FOG LIGHTS (PROJAB)

ADJUSTMENT OF FRONT SEAT BELTS

FIXED HEIGHT SEATBELTS (CEAVFX)

AIR DUCT TO REAR SEATS

WITHOUT AIR DUCT TO REARS (SAIRAR)

AIRBAG CANCEL

DECONNEX AIRBAG PASS (AIRBDE)

ALCOHOL INTERLOCK

NO ALCOHOL INTERLOCK (NOAIS)

ANTENNA TYPE

CONTEXT CRITERIOM (SANA07)

ANTI-LOCK BRAKING SYSTEM

WITH ANTI-LOCK BRAKING SYSTEM (ABS)

BATTERY POWER TRACTION

WIHTOUT BATTERY ENERGY (SSCABA)

BLIND SPOT DETECTION

WITHOUT DECTECTOR BLIND S (SDANGM)

BRAKING ASSISTANCE

EMERG BRAKI WITH WARN LAM (AFUAFD)

CAR SHARING FEATURE

COMPLEMENTARY OBJECT (NOF90)

CENTER CONSOLE

CONSOLE STORAGE TYPE 1 (CSRBA1)

CERTIFICATION EVOLUTION

NO CERTIFICATION EVOLUT (NOEVC)

CKD GROUPING ZONE

COMPLEMENTARY OBJECT (NO031)

CLIMATIC CONSTRAINT HOT COUNTRY

WO CLIMAT CONST WARM COUN (SSCCPC)

COLOR OF OUTSIDE MIRROR

BODY COLOR EXTERIOR REARV (RETC)

COMBI METER

ANALOG/NUMERIC INSTRUM (MET02)

COMMERCIAL EVENT

COMPLEMENTARY OBJECT (SANF80)

COMMERCIAL EVENT 1

COMMERCIAL EVENT TYPE A (PRUPTA)

COMMERCIAL EVENT 2A

WITHOUT NEW GAMME (SNVGAM)

COMMERCIAL EVENT MANAGEMENT 3

COMPLEMENTARY OBJECT (SANF78)

COMMERCIAL VERSION SUPPLEMENT

BASIC COMMERCIAL VERSION (VNOR)

COMMERCIAL VERSION SUPPLEMENT 5

WO COMMERCIAL VERSION (VSNOR)

COMMERCIAL VERSION SUPPLEMENT1

WITHOUT VERSION COMPLEMEN (SAN713)

CONDITIONING

STANDARD PROTECTION (COND0)

COUNTER UNIT

KILOMETRES (KM)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION

TECH REG : NORTH EAST EUR (TL02A)

CUSTOMIZED VERSION

NO CUSTOMIZED VERSION (NOADT)

DAYTIME RUNNING LIGHTS

DAYTIME RUNNING LIGHTS 2 (FDIU2)

DOOR OPENING REMOTE CONTROL TYPE

DOOR OPENING/CLOSING WITH (SOPC2C)

DOOR SECURITY

DOOR.LOCK.BY RUNNING (COPOR)

DRIVE RECORDER

NO DRIVE RECORDER (WOSRE)

DRIVER ATTENTION ALERT

WITHOUT PRESTATION (SPRDEN)

DRIVER'S HANDBOOK

RUMANIAN GLOVE BOX LITERA (NOTROU)

DRIVING ASSISTANCE

DRIVING ASSISTANCE : VEHI (ADAC)

DRIVING MODE CONTROL

WITHOUT MULT EXP (SSMLEX)

DUST PROTECTION

WITH DUST KIT (KITPOU)

ECONOMIC DRIVING

WITH ECO MODE (ECOMOD)

ELECTRIC TOLL COLLECTION

WO ELECTRONIC TOLL SYS SP (SSPTLP)

ELECTROMOTOR DOOR LOCKING

ELECTRIC DOOR LOCKING (CPE)

ELECTRONIC ARCHITECTURE

EL ARCH C1A RUN2 (AC1A2)

ELECTRONIC STABILITY PROGRAM

DIRECT STAB CON HILL ASST (ESPHSA)

EMERGENCY CALL AND BREAKDOWN

WITH EMERGENCY CALL (RCALL)

ENGINE PRODUCTION PLANT

(U) PITESTI (ROMANIA) (APV002_U)

EVOLUTION TECHNIQUE W

NO EVOLUTION TECHNIQUE W (NOTCW)

EXTERIOR REAR VIEW MIRRORS

DOOR MIRRORS 03 (RET03)

FAST TRACK

COMPLEMENTARY OBJECT (NOH70)

FIRE EXTINGUISHER

WITHOUT FIRE EXTINGUISHER (SEXTIN)

FORWARD EMERGENCY BRAKING

ADV EM BRAKING URBAN 1 (AEBS01)

FRONT AND REAR BODY CROSSMEMBER

WIHTOUT CROSSMEMBER (SSRCAR)

FRONT SEAT BELT PRETENSIONER

FRONT SEAT BELT WITH PRET (PTCAV)

FRONT SEAT SUITABLE FOR CHILDREN

ISOFIX SEAT (ISOFIX)

FRONT SEAT TYPE

FRONT SEAT TYPE N 04 (SGAV04)

FRONT SIDE AIRBAG

FRONT SIDE AIRBAG + HEADS (ABLAVI)

FRONT TYRES

185/65 R15 (88)H, 6.00 J 15 - 40 C1 A

FUEL CAP

CAP WITH KEY (BOUCLE)

GEAR SHIFT INDICATOR

WITH GEAR SHIFT INDICATOR (AVGSI)

GEARBOX PRODUCTION PLANT

(A) CACIA (PORTUGAL) (APV003_A)

GEOGRAPHIC COUNTRY

GEO COUNTRY ROMANIA (ROU01)

HEATED NOZZLES

WITHOUT HEATED NOZZLE (SSHTNZ)

HEATED STEERING WHEEL

NO-HEATED STEERING WHEEL (VOLNCH)

HEATED WINDSHIELD

NON-HEATED WINDSCREEN (PBNCH)

HIGH BEAM ASSIST

NO HIGH BEAM ASSIST (NOAHL)

HIGH MOUNTED STOP LAMP

WITH RAISED BRAKE LIGHT (FSTPO)

HYBRIDE EVOLUTION

HYBRID LEVEL NO EVOLUTION (NOEVH)

INTERIOR COLOUR STYLING

INTERIOR HARMONY 02 (HARM02)

INTERIOR ILLUMINATION

WO ATMOSPHERE LIGHT ROOM (SECAMH)

INTERIOR REAR VIEW MIRROR

RRVIEW MIR DAYLIGHT/NIGHT (RETRJN)

INVARIANT PROCESS SHEET MODEL

MODEL ROUTING SHEET (XJF1TR)

LANE KEEP

W/O LANE DEPARTURE WARNI (SDLIGM)

LUGGAGE BOX

W/O LUGGAGE BOX (SRANCF)

LUGGAGE KICKING PLATE

WO BACK DOOR LW MOLDING (SSEBPC)

LUGGAGE RETAINING DEVICE

WITHOUT A NET FOR HOLDING LUGGAGE (SFIRBA)

LUGGAGE ROOM LIGHTING

LIGHTED LUGGAGE ROOM (LUCOF)

MAKE OF TYRES

TYRE BRAND: UNMARKED FITT (BANAL)

MARKETING VERSION

COMMERCIAL VERSION (VEC079)

MISCELLANEOUS BENEFITS TER

COMPLEMENTARY OBJECT (SAN503)

NAVIGATION MAP

W/O MAPPING (SSMAP)

NAVIGATION/SMARTPHONE IMITATION

COMPLEMENTARY OBJECT (NOG72)

ON-BOARD WARRANTY/SERVICES

SERVICES BOOKLET (DDAVB1)

OPTIONAL FRONT TYRES

195/55 R16 (87)H, 6.50 J 16 - 45 185/65 R15 (88)H, 6.00 J 15 - 40

OPTIONAL REAR TYRES

195/55 R16 (87)H, 6.50 J 16 - 45 185/65 R15 (88)H, 6.00 J 15 - 40

OUTSIDE CAMERA

NO OUTSIDE CAMERA (NOCAM)

OVERSPEED AUDIBLE WARNING DEVICE

WITHOUT EXCESS SPEED HORN (SASURV)

PARKING ASSIST SYSTEM

INTELLIGENT PARK SYS 01 (ITPK1)

PARKING BRAKE TYPE

WITHOUT AUTOMATIC PARKING (SSFRPA)

PASSENGER COMPARTMENT HEATING TYPE

AIR-CONDITIONING TYPE N1 (CA01)

PASSENGER COMPARTMENT THERMAL REQUIREMENT

WITHOUT PASSENGER COMPARTMENT THERMAL REQUIREMENT (STHABT)

PLANT ASSEMBLY LINE

ASSEMBLY LINE 2 (CHMON2)

PLANT MARKING FOR COMPLEX START

COMPLEMENTARY OBJECT (SAN593)

PRESTATION EIGHT

NO PRESTATION (NPRTN)

PRESTATION MAPCAR

NO PRESTATION MAPCAR (SMCAR)

PRESTATION SOCIETE

COMPLEMENTARY OBJECT (NOG76)

PRICING

COMPLEMENTARY OBJECT (NOH02)

PROTECTION ELEMENTS

DR+AS AIRBAG (AIRBA2)

RADIO COVER

COMPLEMENTARY OBJECT (NO351)

REAR CARPET - FLOOR

CARPET OF TRUNK (TAPCOF)

REAR CENTRE SEATBELT

3-POINT CENTRE SEATBELT (CMAR3P)

REAR HEADREST TYPE

REAR HEADREST TYPE 3 (ATAR03)

REAR SEAT BELT PRETENSIONER

REAR SEAT BELT WITH PRE-T (PTCAR)

REAR SEAT TYPE

REAR SEAT N 03 (SGAR03)

REAR TYRES

185/65 R15 (88)H, 6.00 J 15 - 40 C1 A

REAR WINDOW

HEATED REAR SCREEN (LAC)

REAR WINDOW CONTROL

MOTOR UNIT (LVAREL)

REGLEMENTARY EVOLUTION

COMPLEMENTARY OBJECT (NOH82)

REVERSING LIGHTS

2 REVERSING LIGHTS (2RVLG)

ROAD SEVERITY

TYPE OF ROAD SEVERITY 2 (TRSEV2)

ROOF RACK/BARS

NO ROOF BARS (SBARTO)

ROOM LIGHTING

W/O ROOM LAMP (SSECLH)

ROUTING SHEETS COUNTRY

ROMANIA (ROUM)

SEAT BELT REMINDER

SEAT BELT WARN TYPE 5 (ALOU5)

SEAT COVERS

FABRIC SEAT-LINING N 03 (DRAP03)

SEAT HEATER AND COOLER

NON-HEATED SEAT (SGSCHA)

SEAT TRIMS

VELVET CLOTH (DRA)

SECURITY DISTANCE GESTION

WO SECUR DIST GEST (SSDWGE)

SERVICE TMC

WITHOUT SERVICE TMC (SSRTMC)

SIDE APPROACH WARNING SYS

WITHOUT SIDE APPROACH WAR (SRDLAT)

SPARE WHEEL

REPAIR INFLATION KIT (KTGREP)

SPECIAL BUILD (FACTORY)

SERIES VEHICLE (WITHOUT S (SERIE)

SPEED LIMITER

COMPLEMENTARY OBJECT (SAN886)

SPRUNG MASS/REAR AXLE

SPRUNG WEIGHT/REAR AXLE 2 (TAR22)

STARTUP CRITERIA

COMPLEMENTARY OBJECT (SAN58A)

STEERING WHEEL HEIGHT ADJUSTMENT

STEERING WHEEL WITH HEIGH (VOLRHP)

STEERING WHEEL MATERIAL

LEATHER STEERING WHEEL (VLCUIR)

STEERING WHEEL POSITION

LEFT (DG)

STORAGE FOR ACCESSORIES

WITHOUT STORAGE FOR ACCES (SRAGAC)

STRIPPING

WITHOUT STRIPPING (SSDECA)

SUSPENDED WEIGHT/FRONT AXLE

SPRUNG WEIGHT/FRONT AXLE2 (TAV23)

TECHNICAL EVOLUTION A

NO TECHNICAL EVOLUTION A (NOTCA)

TECHNICAL EVOLUTION E

NO TECHNICAL EVOLUTION E (NOTCE)

TECHNICAL EVOLUTION G

COMPLEMENTARY OBJECT (NOH22)

TECHNICAL EVOLUTION K

TECHNICAL EVOLUTION K2 (TCHK2)

TECHNICAL EVOLUTION T

TECHNICAL EVOLUTION T0 (TCHT0)

TECHNICAL EVOLUTION V

COMPLEMENTARY OBJECT (NOH90)

TECHNICAL VARIANT FOR ENGINE UNI

COMPLEMENTARY OBJECT (SAN984)

TRUNK INSIDE OPENER TYPE

WO TRUNK INSIDE OPENER (SOUVCF)

TURN SIGNAL LAMP

INDICATORS WITH SIDE REPE (AVREPL)

TYPE OF CLIMATE

TEMPERATE CLIMATE (TEMP)

TYPE OF FRONT WINDOW WINDER

DRIVER: PULSE ELECTRICAL / PASSENGER: SIMPLE ELECTRICAL (LVCIPE)

TYPE OF HEADLIGHTS

LED HEADLAMP (LEDH2)

TYPE OF REFRIGERANT GAS

GAS TYPE 1234YF (1234Y)

TYPE OF TIRES

STANDARD TYRE (PNSTRD)

TYPES OF RADIOS

ULC 4.5 DA (RA47D)

TYRE PRESSURE DETECTION

INDIRECT TIRE PRES MONIT (TPRM3)

UNDERBODY PROTECTION

WITH ANTIGRIT PROTECTION (KITGRV)

UNIVERSAL INTERCONNECT FUNCTION

ALLIANCE IN VEHICLE CONNE (AIVCT)

UTILITY ADAPTATION COVER

WITHOUT ADAPTATION (SAN164)

UTILITY ADAPTATION COVER SPECIFI

COMPLEMENTARY OBJECT (NOH64)

VARIOUS FUNCTIONS

WITHOUT PRODUCT EQUIPMENT (SSPTPR)

VEHICLE LIGHT CONVERSION

WO LIGHT ADAPTATION SVO (SANCML)

VEHICLE PRODUCTION PLANT

(A) PITESTI (ROMANIA) (APV001_A)

VEHICLE TRACKING SYSTEM

COMPLEMENTARY OBJECT (SAND41)

VEHICULE TRANSFORMATION

COMPLEMENTARY OBJECT (SAND30)

WATER PROTECTION

WITH RAIN FORD RIVER KIT (KITPGR)

WHEEL DISC PROTECTION

WITHOUT PROTECTIVE REAR B (SPRODI)

WHEEL RIM TYPE

15 METAL WHEEL RIMS 1 (RTOL15)

WHEELS RIMS

DIFFERENT WHEEL 04 (RDIF04)

WINDOW TINT

TINTED WINDOWS (VT)

WIPER START-UP TYPE

AUTOMATIC LIGHTS + WINDSCREEN WIPER (ALEVA)

WIRELESS PHONE CHARGE

WO TELEPHONY ACCES REFIL (SREACT)

Cronologie

S-au găsit 3 înregistrări

Ultimele înregistrări

2022-11  **Țară necunoscută**



A fost fabricat

Țara (sau statul) indică fie locația centrului de producție, uzina de asamblare sau adresa de înregistrare a producătorului. Data poate fi aproximativă.

2022-12  **România**



A fost înmatriculat

Înregistrarea reprezintă un eveniment administrativ. Acest lucru ar putea fi legat de o schimbare de proprietar, documente etc

2023-09  **România**



Daună detectată



Avem indicii potrivit cărora acest vehicul a fost recunoscut ca avariat în această țară (sau stat). Pentru detalii, vă rugăm să consultați secțiunea „Daune”.



+31

Surse de date

Am verificat 900+ de surse de date în **35 de țări**